

## Sample Summary

Client: Ecology and Environment, Inc.  
Project/Site: EE-004439-Laboratory BOA

TestAmerica Job ID: 580-50288-2

Lab Sample ID	Client Sample ID	Matrix	Collected	Received
580-50288-3	15053103	Water	05/29/15 09:40	05/29/15 17:15

1

2

3

4

5

6

7

8

9

10

11